

BRAMPTON ISLAND

THE WHITSUNDAYS - QUEENSLAND



VOYAGES
BRAMPTON ISLAND
GREAT BARRIER REEF



BRAMPTON ISLAND

Via Mackay
Queensland



AERODROME FACT SHEET

Aerodrome	Brampton Island, Queensland (YBMI)	AVFAX CODE 4407
Category	Unlicensed Aerodrome	
Owner / Operator	Brampton Island Pty Ltd Via Mackay QLD 4740	
Location	Latitude 20 48.2°S, Longitude 149 16.2°E, WAC 3235, VAR 9 DEG E.	
Elevation	37ft AMSL	
Runway	14/32 (141 MAG°) 804m x 16m sealed	
Runway Strip	804m x 50m (graded 45)	
Slope	0.6% down to NW	
Lighting	PTBL EMERGY only.	
Radio Procedures	Communication is with Brisbane Centre 135.5 in circuit area. Contact Brampton Island on 128.8 inbound with ETA and intentions. The Aircraft must radio Brampton Island 10 minutes prior to landing.	
Fuel	No refuelling facilities available.	
Parking	The apron area is located on the north western end of the runway. Aircraft should proceed beyond the RPT apron to the parking area. Overnight parking and portorage fees apply to non-house guests.	
Landing Permits	A landing permit is required. Any permit issued will be for one landing only. An application should be made 24 hours prior to: Front Office Manager Brampton Island Resort Phone: 07 4951 4499 / Fax: 07 4951 4097	
Landing Fee	A fee of \$150.00 (inclusive of GST) is payable for each landing. This fee is waived for guests staying at the resort.	

Operational Restrictions & Notices

- The aerodrome and circuit area are subject to severe turbulence in strong wind conditions.
- Overfly aerodrome to assess wind conditions and runway availability prior to joining circuit. Use landing lights in circuit area.
- Right hand circuits when OPR RWY 32.
- Watersport operations are conducted to the north west of the runway. Ensure there will be no conflict prior to approach RWY 14 or take off RWY 32.
- Joy flights and flying training are not permitted.
- Operations by aircraft above 5700kg are not permitted.
- All aircraft must use Turning nodes for 180 turns on runway.
- RWY 14/32 transitional SFC infringed by trees on both sides of the RWY.
- Inner HZS infringed by hills to the SW of AD. OBST lights not provided.
- RWY 14 SOT commences at RWS end. ASDA ends at RWS end.
- RWY 14 curved take-off path AVBL. Obstruction data AVBL from AD OPR.
- RWY 32 SOT commences at RWS end. ASDA ends at RWS end.
- RWY 32 curved take-off path AVBL. Obstruction data AVBL from AD OPR.

This information is issued by Voyages and supersedes any previously published briefing sheets. The information is correct at time of printing but the pilot in command is responsible for checking the accuracy of the details and serviceability of the aerodrome prior to the operation. Voyages accepts no responsibility for the security or safety of any aircraft while operating at the aerodrome.

Valid as at June 09



Voyages Hotels & Resorts Pty Ltd
A.B.N 24 079 925 036
GPO Box 3589
Sydney NSW 2001 AUSTRALIA
Website: www.voyages.com.au

Voyages (Australia)
Telephone: 1300 134 044
Facsimile: 02 9299 2103
Email: travel@voyages.com.au

Voyages (Internationally)
Telephone: +61 2 8296 8010
Facsimile: +61 2 9299 2103
Email: travel@voyages.com.au